


Category C - Phase II of GWF Tracy

- h)** A three-phase fault with a normal 4-cycle clearing time at the Tesla 500 kV bus, followed by a simultaneous loss of the Tesla-Tracy and Tesla-Los Banos 500 kV lines.

Plot 1	Project Terminal Voltages and Angles
Plot 2	Project Power and Speed
Plot 3	Selected Bus Voltages Adjacent to Fault
Plot 4	Selected Bus Frequencies Adjacent to Fault

	GENERAL ELECTRIC COMPANY	1	Mon Aug 27 09:50:56 2001
C:\GENF\ph2\cat\H\H_Tesla-Tracy&LsBns chf			
C:\GENF\04\hs-115-3b-tyd.sav			




GENF Tracy Peaking Plant Project (Phase 2 - 258 MW)
 2004 Summer Peak Base Case, Stability Study
 Phase 2 w/ GENF CT 1 & 2 and ST each @ 86.0 MW
 Tracy - Tesla and Tesla - Los Banos 230 kV DLO
 3 phase 4 cycle fault at Tesla 230 kV bus

GENERAL ELECTRIC COMPANY


2

Mon Aug 27 00:04:05 2001


C:\GENF\Ph2\Cat\H\H_Tesla-Tryg&LsBns.chf
C:\GENF\04\hs-115-3b-tryd.sav



GENF Tracy Peaking Plant Project (Phase 2 - 258 MW)
2001 Summer Peak Base Case, Stability Study
Phase 2 w/ GENF CT 1 & 2 and ST each @ 86.0 MW
Tracy - Tesla and Tesla - Los Banos 230 kV DLO
3 phase 4 cycle fault at Tesla 230 kV bus



GWF Tracy Peaking Plant Project (Phase 2 - 258 MW)
2004 Summer Peak Base Case, Stability Study
Phase 2 w/ GWF CT 1 & 2 and ST each @ 86.0 MW
Tracy - Tesla and Tesla - Los Banos 230 kV DLO
3 Phase 4 cycle fault at Tesla 230 kV bus



GWF Tracy Peaking Plant Project (Phase 2 - 258 MW)
 2004 Summer Peak Base Case, Stability Study
 Phase 2 w/ GWF CT 1 & 2 and ST each @ 86.0 MW
 Tracy - Tesla and Tesla - Los Banos 230 kV DLO
 3 Phase 4 cycle fault at Tesla 230 kV bus